

FIGURE 1

## Brinell hardness after humidifying




FIGURE 2

Wear resistance to abrasion, loss of mass in g





FIGURE 3






FIGURE 4




FIGURE 5